

#### Description

This kit is used to install a fibre cable into ports of the closure. The kit contains a heat shrink port that enables the cable to be heat shrunk onto a port which can then be plugged into one of the circular ports in the base of the joint.

#### **Tools Required**

#### Tools:


1.Gas Torch or Hot Air2.Cable Sheath Stripper3.Fibre stripping tools4.Large Screwdriver5.Scissors6.Pen




#### **Component Parts (pictures not to scale)**











Page 4 of 14









Page 6 of 14












Page 9 of 14





Page 10 of 14






- Choose the appropriate port then push the gland into the base until resistance is felt on the O rings.
- Continue pushing with a twisting action until an audible click is heard.
- Visually check from inside the base that all three locking tabs have clicked into place.

Step 9






Page 12 of 14

IP574





Page 13 of 14



